

Drilling Log		10. Size and Type of Bit	
1. Project KHV		11. Datum for Elevation Shown (TOM or MSL) MLLW	
2. Location 770713.80E, 227991.20N		12. Manufacturer's Designation of Drill	
3. Drilling Agency Alpine Ocean Seismic Survey, Inc.		13. Total No. of Overburden Samples Taken	
4. Hole No. (As shown on drawing use) KHV-57		Disturbed	
5. Name of Owner		Undisturbed	
6. Direction of Hole		14. Total No. of Core Boxes	
<input checked="" type="checkbox"/> Vertical <input type="checkbox"/> Inclined _____ Degree from Vertical		15. Elevation Ground Water	
7. Thickness of Overburden		16. Date Hole	
8. Depth Drilled into Rock		Started 6/10/93 Completed 6/10/93	
9. Total Depth of Hole 19.7 ft		17. Elevation Top of Hole -39.9'	
		18. Total Core Recovery for Boring %	
		19. Signature of Inspector JV MC	

Elevation	Depth	Legend	Classification of Materials (Description)	% Core Recovery	Box or Sample No.	Remarks (Drilling time, water loss, depth of weathering, if significant)
a	b	c	d	e	f	g
	0	SC	Dark gray-brown clayey sand			Sample at 1.7'
	1					
	2					
	3	SC	Dark gray clayey sand			Sample at 7.7'
	4					
	5					
	6					
	7	SC	Dark gray clayey sand			
	8					
	9					
	10					

382

Drilling Log (Cont Sheet)		Elevation Top of Hole -39.9'		Hole No. KHV-57		
Project KHV		Installation		Sheet of 2 Sheets		
Elevation	Depth	Legend	Classification of Materials (Description)	% Core Recovery	Box or Sample No.	Remarks (Drilling time, water loss, depth of weathering, if significant)
a	b	c	d	e	f	g
	10	SC	Dark gray clayey sand			
	11					
	12					
	13	SC	Dark gray-brown clayey sand			
	14					
	15					
	16	SC	Dark gray-brown clayey sand			
	17					
	18					Sample at 18.0'
	19		19.7 ft Recovery			
	20					
	21					

384