STATE OF DELAWARE **DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS**

F.A. Project: S.R. 26, Atlantic Avenue from Clarksville to Assawoman Canal

Contract: 24-112-10

Boring Location: Sta. 145+90, 20' Rt. C.L.

Boring Surface Elev.:

Reference:

Wt. of Casing Hammer: Wt. of Sample Hammer: Type of: D-Sampler: S-Sampler: U-Sampler: Average Fall: Average Fall: O.D. of Sampler: O.D. of Samp. Tube: O.D. of Samp. Tube: O.D. of Rock Core: Lbs. IN. IN. IN. Lbs. 30 Split-Barrel O.D. O.D. Ö.D. O.D. Core Bit:

Casing Size:
Hollow Stem Auger: Inches

From Depth of: From Depth of:

To: To: 0.0

6.0

Boring No.: RB#66

Water Level Readings Date 5/17/2006

Time 9:00 a.m. Depth of Hole 6.0'

Depth of Casing 4.0'

No. of:

Core Drilling in Rock:

Depth of Water 5.75'

Elev. of Water -5.8

Pay Quantities: 2 1/2 in. Dia. Dry Sample Boring: No. of 2 in. Dia. Sheiby Tubes: 2 1/2 in. Dia. Contin. Sample Boring:

8.0

Ft.; Ft.:

Dia. U-Sample Boring: U-Samples:

Ft. Ft.

Boring Contractor: Walton Corporation Driller: Dave Burt

Helpers: Jason Truver & Wayne Hurd

Depth (ft.)	Daily Progress	No.	Sample Depth	Blows/6"	Sample Description	Class./G.I.	Remarks
3		1	2.0'	2 4 6 4	Moist loose brown silty fine sand w/some coarse sand.	A-2-4(0)	
!		2	3.3' 4.0'	3 5	Moist loose brown fine to coarse sand w/	A-2-4(0)	
		2A	4.0' 5.3'	33	some silt. 12" RECOVERY Wet firm multicolored silty fine sandy clay	A-6(7)	
6			6.0'		w/trace of coarse sand.		
		3	6.0'	3 5 6 7	Saturated stiff multicolored silty fine sandy clay.	A-6(9)	
		4	8.0' 8.0'	3	16" RECOVERY	1 4(4)	
9		7	0.0	3 5 7 10	Saturated stiff grayish red clayey fine sandy silt.	A-4(4)	:
			10.0'		24" RECOVERY		
12					-		
15							
						;	
18							

Remarks:

KEY TO SYMBOLS

Symbol Description

Strata symbols

•	•		•	•	

Silty sand



Sand



Low plasticity clay



Silt

Notes:

- 1. Exploratory borings were drilled on 5-17-2006 using a 3 1/4-inch diameter hollow stem auger.
- 2. No free water was encountered at the time of drilling or when re-checked the following day, unless recorded on 1st page.
- 3. Boring locations were taped from existing features and elevations extrapolated from survey unless otherwise reported.
- 2. These logs are subject to the limitations, conclusions, and recommendations in this report.
- 5. Results of tests conducted on samples recovered are reported