

INTERVAL SHEET

WWCR: 70

Page 1 of 1

VDMR Well No: 1890

Date rec'd: 6/7/67

Sample Interval: from 0' to: 160'

PROP: Dickinson Fire Brick #1

Number of samples: 16

COMP: Sydnor Hydrodynamics

Total Depth: 167'

COUNTY: Rockbridge (Buena Vista)

Oil or Gas: Water: Exploratory:

From-To	From-To	From-To	From-To
0 - 10	-	-	-
10 - 20	-	-	-
20 - 30	-	-	-
30 - 40	-	-	-
40 - 50	-	-	-
50 - 60	-	-	-
60 - 70	-	-	-
70 - 80	-	-	-
80 - 90	-	-	-
90 - 100	-	-	-
100 - 110	-	-	-
110 - 120	-	-	-
120 - 130	-	-	-
130 - 140	-	-	-
140 - 150	-	-	-
150 - 160	-	-	-
No Sample	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-

All intervals have both washed and unwashed samples

OWNER: Dickinson Fire Brick Co. (Well #1)  
DRILLER: Sydnor Hydrodynamics, Inc.  
COUNTY: Rockbridge (Buena Vista)

VDMR: 1890  
WWCR: 70  
TOTAL DEPTH: 167'

GEOLOGIC LOG

Depth in feet

0-10	Sandstone - grayish-pink, fine-grained, well rounded grains; some orthoquartzite
10-20	Orthoquartzite - pale-red, medium-grained
20-30	"
30-40	" much sand, trace limonite
40-50	" "
50-60	" "
60-70	" "
70-80	"
80-90	" much sand
90-100	"
100-110	"
110-120	"
120-130	"
130-140	" much sand
140-150	" "
150-160	"
160-167	No Sample

GEOLOGIC SUMMARY

Rock Unit

Age

Erwin Formation

Cambrian

Virginia Division of Mineral Resources  
W. W. Winters, Geologist  
September 1967

INTERVAL SHEET

WWCR: 70

Page 1 of 1

VDMR Well No: 1890

Date rec'd: 6/7/67

Sample Interval: from 0' to: 160'

PROP: Dickinson Fire Brick #1

Number of samples: 16

COMP: Sydnor Hydrodynamics

Total Depth: 167'

COUNTY: Rockbridge (Buena Vista)

Oil or Gas: Water:  Exploratory:

From-To	From-To	From-To	From-To
0 - 10	-	-	-
10 - 20	-	-	-
20 - 30	-	-	-
30 - 40	-	-	-
40 - 50	-	-	-
50 - 60	-	-	-
60 - 70	-	-	-
70 - 80	-	-	-
80 - 90	-	-	-
90 - 100	-	-	-
100 - 110	-	-	-
110 - 120	-	-	-
120 - 130	-	-	-
130 - 140	-	-	-
140 - 150	-	-	-
150 - 160	-	-	-
No Sample	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-
-	-	-	-

All intervals have both washed and unwashed samples

OWNER: Dickinson Fire Brick Co. (Well #1)  
DRILLER: Sydnor Hydrodynamics, Inc.  
COUNTY: Rockbridge (Buena Vista)

VDMR: 1890  
WWCR: 70  
TOTAL DEPTH: 167'

GEOLOGIC LOG

Depth in feet

0-10	Sandstone - grayish-pink, fine-grained, well rounded grains; some orthoquartzite
10-20	Orthoquartzite - pale-red, medium-grained
20-30	"
30-40	" much sand, trace limonite
40-50	" "
50-60	" "
60-70	" "
70-80	"
80-90	" much sand
90-100	"
100-110	"
110-120	"
120-130	"
130-140	" much sand
140-150	" "
150-160	"
160-167	No Sample

GEOLOGIC SUMMARY

Rock Unit

Erwin Formation

Age

Cambrian

Virginia Division of Mineral Resources  
W. W. Winters, Geologist  
September 1967