

OWNER: Brun's
DRILLER: Farmville Well Drilling Co., Inc.
COUNTY: Buckingham (Howardsville)

VDMR: 1782
WWCR: 136
TOTAL DEPTH: 262'

GEOLOGIC LOG

Depth in feet

0-102	No samples
102-122	Sandy siltstone - red-brown, strong iron-oxide staining, fine-grained, subangular to rounded, poorly-sorted sand grains; silt and minor amounts of clay, considerable quartz and lithic material, and some feldspar
122-142	" with some greenstone fragments
142-162	" "
162-182	" "
182-202	"
202-222	"
222-242	"
242-262	"

GEOLOGIC SUMMARY

	<u>Rock Unit</u>	<u>Age</u>
0-102'	No samples	
102-262'	Newark Group	Triassic

Virginia Division of Mineral Resources
Robert G. Willson, Geologist
January 5, 1968