

Slope Stability—Bluegrass Hills Region



Remnants of a slide seen at the base of this roadcut along Ky. 8 in Bracken County reveal the instability of shales overlying limestone. Slope stability presents problems to development in the Bluegrass Hills Region. Photo by, Dan Carey, Kentucky Geological Survey.