

Dc53-178

| BORING 7 | | BORING 8 | |
|---------------|------------|-----------------------------|---|
| | | SURFACE ELEVATION 16.5 FEET | |
| DEPTH IN FEET | BLOW COUNT | SYMBOLS | DESCRIPTIONS |
| 0 | 5 | SM | DARK BROWN FINE SAND, TRACE SILT (LOOSE) |
| 5 | 6 | SM | DARK BROWN SILTY FINE SAND TO FINE SANDY SILT, TRACE RICA (LOOSE) |
| 10 | 11 | SM | GRADING TO BROWN FINE SAND, LITTLE SILT (MEDIUM DENSE) |
| 15 | 16 | SM | |
| 20 | 17 | SM | DARK GRAY SILTY FINE SAND TO FINE SANDY SILT, TRACE RICA (MEDIUM DENSE) |
| 25 | 17 | SM | |
| 30 | 8 | | GRADING LOOSE |
| 35 | | | |

Qc1
not
present

BORING COMPLETED TO 311' ON 6-14-78.
DRILLING WITH BENTONITE.
1 1/2" OF 1 1/2" DIA. PVC. PIPE PLACED IN HOLE AFTER BORING.
CRACKING WATER LEVEL OBSERVED IN THE BORE HOLE AT DEPTH OF 6.25' ON 6-21-78.

BORING 10

LOG OF BORING