

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 7

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 33+50, 18' Lt. CENTERLINE

Oc 25-23

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS	
11/2/04	1	1.0'	20	Moist very dense brown coarse sandy gravel w/trace of silt and fine sand.	A-1-a (0)		
		2.0'	27				
----- 12" Recovery -----							
	2	2.0'	15	Wet very stiff brown fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)		
			10				
			7				
		4.0'	7				
----- 20" Recovery -----							
	3	4.0'	6	Saturated stiff brownish gray silt w/some fine sand, trace of coarse sand, gravel and clay.	A-4 (0)		
			6				
			7				
		6.0'	9				
----- 22" Recovery -----							
	4	6.0'	9	Saturated very stiff brown fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)		
			7				
			13				
		8.0'	12				
----- 20" Recovery -----							
	5	8.0'	14	Saturated very stiff brown fine to coarse sand w/trace of silt and gravel.	A-3 (0)		
			12				
			13				
		10.0'	14				
----- 22" Recovery -----							
(END)							



BORING NO. B # 7
SURFACE ELEV. + 41.8'