

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 22

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 330+00, CENTERLINE

0025-26

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/2/04	1	0.7'	2	Wet firm brown silty coarse to fine sandy clay w/trace of gravel.	A-6 (1)	
			3			
			4			
		2.0'	4			
----- 18" Recovery -----						
	2	2.0'	2	Wet loose brown coarse to fine sand w/some silt, trace of gravel.	A-1-b (0)	
			2			
		4.0'	5			
----- 22" Recovery -----						
	3	4.0'	4	Wet medium dense brown coarse to fine sand w/some silt, trace of gravel.	A-1-b (0)	
			8			
			6			
		6.0'	6			
----- 22" Recovery -----						
	4	6.0'	5	Wet loose brown coarse to fine sand w/some silt, trace of gravel.	A-1-b (0)	
			5			
		8.0'	4			
----- 22" Recovery -----						
	5	8.0'	3	Saturated loose brown coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			3			
		10.0'	2			
----- 24" Recovery -----						

( END )

ist

BORING NO. B # 22  
SURFACE ELEV. + 38.4'