

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 8

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 136+00, 14' Lt. CENTERLINE

0c25-29

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.3'	5	Moist medium dense brown gravelly fine sand and silt w/some coarse sand.	A-2-4 (0)	
			8			
			18			
		2.0'	15			
20" Recovery						
	2	2.0'	11	Wet stiff brown fine sandy silt w/some coarse sand, trace of gravel and clay.	A-4 (0)	
			5			
			5			
		4.0'	7			
22" Recovery						
	3	4.0'	4	Wet loose brown fine sand w/some silt, trace of coarse sand and gravel.	A-2-4 (0)	
			5			
			4			
		6.0'	5			
24" Recovery						
	4	6.0'	5	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
			4			
			2			
		8.0'	2			
24" Recovery						
	5	8.0'	2	Saturated loose brown silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
			2			
			3			
		10.0'	2			
22" Recovery						
( END )						

BORING NO. B # 8  
SURFACE ELEV. + 42.0'