

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 12

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 142+00, 12' Rt. CENTERLINE

0c25-31

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/2/04	1	0.7'	1	Moist very loose brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
			1			
			2			
		2.0'	2			
22" Recovery						
	2	2.0'	4	Moist loose brown fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
			4			
			5			
		4.0'	4			
24" Recovery						
	3	4.0'	4	Wet stiff brownish gray fine sandy silt w/some coarse sand and clay, trace of gravel.	A-4 (0)	
			5			
			7			
		6.0'	6			
20" Recovery						
	4	6.0'	4	Saturated stiff brownish gray fine sandy silt w/trace of coarse sand, gravel and clay.	A-4 (0)	
			7			
			7			
		8.0'	9			
20" Recovery						
	5	8.0'	7	Saturated medium dense brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
			8			
			7			
		10.0'	4			
24" Recovery						

( END )

BORING NO. B # 12  
SURFACE ELEV. + 42.1'