

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 19

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 230+00, CENTERLINE

0c25-33

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.8'	7	Moist medium dense brown fine to coarse	A-2-4 (0)	
			8	sand w/some clay, trace of gravel.		
			9			
		2.0'	4			
----- 21" Recovery -----						
	2	2.0'	4	Wet stiff brownish gray fine sandy silt	A-4 (4)	
			4	w/some clay, trace of coarse sand and		
			6	gravel.		
		4.0'	8			
----- 20" Recovery -----						
	3	4.0'	8	Saturated very stiff brownish gray silt	A-4 (5)	
			7	w/some fine sand and clay, trace of		
			11	gravel.		
		6.0'	14			
----- 24" Recovery -----						
	4	6.0'	7	Saturated very stiff brownish gray fine	A-4 (0)	
			12	sandy silt w/some coarse sand and clay,		
			15	trace of gravel.		
		8.0'	16			
----- 20" Recovery -----						
	5	8.0'	14	Saturated medium dense brown silty fine	A-2-4 (0)	
			12	sand w/some coarse sand, trace of gravel.		
			8			
		10.0'	9			
----- 22" Recovery -----						

(END)

BORING NO. B # 19
SURFACE ELEV. + 41.9'