

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. SWM # 2

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 19+07, 127' Lt. CENTERLINE

OC 25-35

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.6'	1	Wet firm brownish gray fine sandy silt w/some coarse sand and clay, trace of gravel.	A-4 (0)	
			3			
			3			
		2.0'	4	17" Recovery		
	2	2.0'	3	Wet stiff gray fine sandy silt w/some coarse sand and clay, trace of gravel.	A-4 (0)	
			6			
			6			
		4.0'	8	20" Recovery		
	3	4.0'	6	Wet stiff brown fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)	
			7			
			8			
		6.0'	9	24" Recovery		
	4	6.0'	6	Saturated loose brown silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
			5			
			5			
		8.0'	4	22" Recovery		
	5	8.0'	3	Saturated loose brown silty fine sand w/trace of coarse sand.	A-2-4 (0)	
			3			
			2			
		10.0'	3	24" Recovery		

(END)