

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 20

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 239+00, CENTERLINE

0c 25-37

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.5'	3	Wet loose brown fine to coarse sand w/some gravel, trace of clay.	A-2-4 (0)	
		2.0'	3			
			4			
----- 18" Recovery -----						
	2	2.0'	3	Wet loose gray silty coarse to fine sand w/trace of gravel.	A-2-4 (0)	
			3			
		4.0'	4			
----- 24" Recovery -----						
	3	4.0'	7	Wet medium dense gray silty coarse to fine sand w/trace of gravel.	A-2-4 (0)	
			7			
		6.0'	5			
----- 22" Recovery -----						
	4	6.0'	5	Saturated loose brown silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
			3			
		8.0'	4			
----- 22" Recovery -----						
	5	8.0'	4	Saturated loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
			5			
		10.0'	5			
----- 16" Recovery -----						
(END)						

BORING NO. B # 20
SURFACE ELEV. + 39.8'