

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 13

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 148+00, 3' Lt. CENTERLINE

0c25-39

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/4/04	1	0.6'	4	Wet firm gray fine sandy silt w/some clay and coarse sand, trace of gravel.	A-4 (0)	
			4			
			4			
		2.0'	4			
22" Recovery						
	2	2.0'	4	Wet stiff gray fine sandy silt w/some clay and coarse sand, trace of gravel.	A-4 (0)	
			5			
			7			
		4.0'	8			
20" Recovery						
	3	4.0'	6	Wet medium dense brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
			6			
			6			
		6.0'	6			
18" Recovery						
	4	6.0'	4	Saturated loose brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
			5			
			4			
		8.0'	3			
22" Recovery						
	5	8.0'	3	Saturated loose brown coarse to fine sand w/some silt, trace of gravel.	A-1-b (0)	
			4			
			3			
		10.0'	4			
18" Recovery						

(END)

BORING NO. B # 13
SURFACE ELEV. + 38.6'