

STATE OF DELAWARE  
 DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 15

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
 BORING LOCATION: STA. 314+00, CENTERLINE

OC 25-42

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/3/04	1	0.7'	2	Wet stiff brownish gray fine sandy silt	A-4 (0)	
			4	w/some coarse sand and clay, trace of		
			5	gravel.		
		2.0'	4			
20" Recovery						
	2	2.0'	3	Wet firm brownish gray fine sandy silt	A-4 (1)	
			4	w/some coarse sand and clay, trace of		
				gravel. (12" Sample )		
	2A		9	Wet medium dense brown fine to coarse sand	A-2-4 (0)	
		4.0'	8	w/some silt, trace of gravel. ( 10" Sample )		
22" Recovery						
	3	4.0'	10	Wet medium dense brown coarse to fine sand	A-3 (0)	
			12	w/trace of silt.		
			14			
		6.0'	14			
22" Recovery						
	5	6.0'	9	Wet medium dense brown fine to coarse sand	A-3 (0)	
			10	w/some gravel, trace of silt.		
			13			
		8.0'	12			
20" Recovery						
	5	8.0'	10	Wet medium dense brown coarse to fine sand	A-2-4 (0)	
			9	w/some silt, trace of gravel.		
			9			
		10.0'	18			
22" Recovery						
( END )						

BORING NO. B # 15  
 SURFACE ELEV. + 38.5'