

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 3

BORING NO. S # 3A

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 313+63, 40' Rt. CENTERLINE

Oc 25-45

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/3/04	1	4.0'	7	Wet very stiff brown fine to coarse sandy silt w/trace of gravel.	A-4 (0)	
			11			
			10			
		6.0'	10			
----- 20" Recovery						
	2	9.0'	4	Wet loose brown silty coarse sand w/some fine sand, trace of gravel.	A-1-b (0)	
			4			
		11.0'	4			
----- 22" Recovery						
	3	14.0'	2	Saturated loose brown coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			3			
		16.0'	5			
----- 24" Recovery						
	4	19.0'	3	Saturated loose brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
			4			
		21.0'	3			
----- 16" Recovery						
	5	24.0'	2	Saturated loose brown fine to coarse sand w/trace of gravel and silt.	A-3 (0)	
			3			
		26.0'	4			
----- 18" Recovery						
	6	29.0'	4	Saturated loose brown coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			4			
		31.0'	5			
----- 22" Recovery						
	7	34.0'	4	Saturated loose brown coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			4			
		36.0'	4			
----- 22" Recovery						

BORING NO. S # 3A  
SURFACE ELEV. + 38.5'