

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 3

BORING NO. S # 5A

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 342+00, 40' Rt. CENTERLINE

Oc 25-48

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/8/04	1	3.0'	4	Saturated stiff gray silt w/trace of fine to coarse sand.	A-4 (0)	
			4			
			5			
		5.0'	4	20" Recovery		
	2	8.0'	3	Saturated medium dense gray fine to coarse sand w/trace of gravel and silt.	A-1-b (0)	
			5			
			6			
		10.0'	5	18" Recovery		
	3	13.0'	2	Saturated loose gray coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			2			
			3			
		15.0'	2	22" Recovery		
	4	18.0'	1	Saturated very loose gray fine sand w/some silt, trace of coarse sand.	A-2-4 (0)	
			1			
			2			
		20.0'	2	22" Recovery		
	5	23.0'	2	Saturated loose gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
			1			
			4			
		25.0'	4	22" Recovery		
	6	28.0'	2	Saturated very loose brown coarse to fine sand w/trace of silt and gravel.	A-1-b (0)	
			2			
			2			
		30.0'	2	20" Recovery		
	7	33.0'	2	Saturated loose brown coarse to fine sand w/trace of gravel and silt.	A-1-b (0)	
			3			
			3			
		35.0'	4	18" Recovery		

BORING NO. S # 5A  
SURFACE ELEV. + 33.5'