

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 3

BORING NO. S # 5B

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 342+00, 40' LT. CENTERLINE

Oc 25-49

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	3.0'	8	Moist medium dense gray silty fine sand	A-2-4 (0)	
			16	w/some coarse sand, trace of gravel.		
			12			
		5.0'	9			
22" Recovery						
	2	8.0'	2	Saturated very loose gray fine to coarse	A-2-4 (0)	
			2	sand w/some silt, trace of gravel.		
			2			
		10.0'	1			
20" Recovery						
	3	13.0'	1	Saturated loose gray coarse to fine sand	A-1-b (0)	
			3	w/trace of silt and gravel.		
			3			
		15.0'	3			
22" Recovery						
	4	18.0'	1	Saturated very loose brown fine to coarse	A-2-4 (0)	
			2	sand w/some silt, trace of gravel.		
			2			
		20.0'	2			
20" Recovery						
	5	23.0'	1	Saturated very loose brown silty fine sand	A-2-4 (0)	
			W/H	w/trace of coarse sand.		
			1			
		25.0'	2			
22" Recovery						
	6	28.0'	2	Saturated loose brown coarse to fine sand	A-1-b (0)	
			3	w/trace of silt and gravel.		
			4			
		30.0'	3			
22" Recovery						
	7	33.0'	4	Saturated loose brown coarse sand w/some	A-1-b (0)	
			4	gravel and fine sand, trace of silt.		
			5			
		35.0'	5			
16" Recovery						

BORING NO. S # 5B
SURFACE ELEV. + 33.5'

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 3 OF 3

BORING NO. S # 5B

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS

BORING LOCATION: STA. 342+00, 40' Lt. CENTERLINE

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	8	38.0'	7	Saturated medium dense brown coarse to fine sand w/some gravel, trace of silt.	A-1-b (0)	
			6			
			6			
		40.0'	6			
				18" Recovery		

(END)

BORING NO. S # 5B
SURFACE ELEV. + 33.5'