

MAIL TO:
 WATER SUPPLY BRANCH
 DIVISION OF WATER RESOURCES
 P.O. BOX 1301
 DOVER, DELAWARE 19003

STATE OF DELAWARE
 DEPARTMENT OF NATURAL RESOURCES
 AND ENVIRONMENTAL CONTROL

ALL COMPLETION REPORTS MUST
 BE RETURNED 21 DAYS AFTER
 CONSTRUCTION DATE

WELL COMPLETION REPORT

PLEASE PRINT

PERMIT NO. 604472 LOCAL ID _____

OWNER Country Club Homeowners

CONSTRUCTION DATE 11-22-80
 PURPOSE TEST ENHANCEMENT

USE DOMESTIC AGRICULTURAL
 COMMERCIAL INDUSTRIAL
 IRRIGATION PUBLIC
 MONITOR DEWATERING
 HEAT PUMP RECHARGE HEAT PUMP SUPPLY
 OTHER (Specify) _____

IS THIS A REPLACEMENT WELL? YES NO
 ABANDONMENT DATE FOR OLD WELL N/A
 ABANDONMENT METHOD N/A

DRILLING METHOD
 AUGERED BORED CABLE TOOL
 DRIVEN JETTED AIR ROTARY
 MUD ROTARY REVERSE WASHED
 OTHER (Specify) _____
 TOTAL DEPTH DRILLED 70'

CASING SEQUENCE

DEPTH	INNER	OUTER
CASING TOP	<u>1" ADIVE</u>	
CASING BOTTOM	<u>65'</u>	
CASING DIAMETER	<u>7"</u>	
CASING MATERIAL	<u>PVC</u>	

SCREEN SEQUENCE

DEPTH	INNER	OUTER
SCREEN TOP	<u>25'</u>	
SCREEN BOTTOM	<u>70'</u>	
SCREEN DIAMETER	<u>4"</u>	
SCREEN MATERIAL	<u>PVC</u>	

WRITTEN APPROVAL FOR SCREENING/
 GRAVEL PACKING MORE THAN ONE ADD-
 ONER MUST BE OBTAINED FROM DNR/EC

GROUT TYPE: CEMENT BENTONITE CLAY
 OTHER _____
 FROM 0 TO 60 FEET
 NON-GROUT BACKFILL OF WELL ANNULUS
 TYPE None FROM _____ TO _____ FEET
 GRAVEL BACK TYPE FB washed
 FROM 60 TO 70 FEET
 STATIC WATER LEVEL: DATE 11-22-80
16.0 FT (Below, above) GROUND SURFACE
 PUMPING WATER LEVEL: _____ FT BELOW GRADE
 AFTER 2 HOURS AT 60 GPM.

WELL HEAD COMPLETION:
 TYPE: PITLESS ADAPTOR
 OTHER _____
 _____ INCHES ABOVE GRADE

TYPE OF PERMANENT PUMP INSTALLED:

PUMP MANUFACTURE _____
 RATED CAPACITY (GPM) _____
 PUMP INTAKE SETTING _____ FT. BELOW GRADE

THE COMPLETED WELL IS?
 YES NO
 A. AT LEAST 5' FROM ANY OVERHANG
 B. AT LEAST 50' FROM ANY SEPTIC TANK
 C. AT LEAST 10' FROM TOWN CENTER LINE
 D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TILE FIELD

THE NEAREST NEIGHBORS (CIRCLE ONE)
 SEPTIC TILE FIELD CESSPOOL OR POND
 IS 20' FROM COMPLETED WELL
 IS COMPLETED WELL LOCATED AS SHOWN
 ON APPLICATION FORM?
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS

DRILLERS LOG DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Medium light brown sand	0'	15'
Medium coarse tan sand	10'	20'
Coarse tan sand	20'	30'
Medium brown sand	40'	50'
Coarse yellow sand	50'	70'

SUPPLEMENTAL DRILLERS LOG ATTACHED YES NO
 PAGE 1 OF 1 PAGES
 COMPANY NAME BURNS Well Drilling
 SIGNATURE OF DRILLER OR CHANGE Richard Farley DATE 11-24-80

Don
0d32-05

DOCUMENT NO. 66-86-75-61-68

WHITE - DNR/EC

CANARY - CONTRACTOR

PINK - OWNER