MAIL TO:

WATER SUPPLY-BRANCH
DIVISION OF ENVIRONMENTAL CONTROL
P.O. BOX 1401
DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED 30 DAYS AFTER CONSTRUCTION DATE

WELL COMPLETION REPORT

0913-04

| PLEASE PRINT | | | | |
|--|--|--|---------------|------------------|
| PERMIT NO. 92934 LOCAL ID | | TYPE OF PERMANENT PUMP INSTALLED: | | |
| OWNER BARBARA A. LicyD | | PUMP MANUFACTURE | | |
| /> / | | RATED CAPACITY (GPM) | | |
| CONSTRUCTION DATE 10/20/92 | | PUMP INTAKE SETTING FT. BELOW GRADE | | |
| PURPOSE: TEST PERMANENT | | THE COMPLETED WELL IS? | | |
| | | | | |
| | | | | /ES NO |
| USE: DOMESTIC AGRICULTURAL | | A. AT LEAST 15' FROM ANY FOUR | NDATION | |
| ☐ COMMERCIAL / ☐ INDUSTRIAL | | B. AT LEAST 50' FROM ANY SEE | PTIC TANK | |
| ☐ IRRIGATION ☐ PUBLIC | | C. AT LEAST 10' FROM TOWN S | EWER LINE | |
| □ OBSERVATION \□ ØEWATERING | | D. AT LEAST 100' FROM THE NE | | |
| | | OF ANY TILE FIELD | AREST EDGE | |
| ☑HEAT PUMP RECHA | | | | |
| OTHER (Specify) | | THE NEAREST NEIG | | |
| IS THIS A REPLACEMENT WELL? YES 🗀 NO 🕮 🗕 | | SEPTIC , TILE FIELD CESS | POOL OR PR | IIVY |
| ABANDONMENT DATE FOR OLD WELL/Y//4 | | IS 100 + FROM COMPLETED WELL. | | |
| ABANDONMENT METHOD | 1 . / 27 | | | |
| ADAINDONMENT METHOD | | IS COMPLETED WELL LOCATED AS SHOWN | | |
| | | ON APPLICATION FORM? | | |
| DRILI | LING METHOD | IF NO, DESCRIBE LOCATION CH | IANGE OR OTHE | ER COMMENTS. |
| ☐ AUGERED ☐ E | BORED CABLE TOOL | | | |
| | JETTED AIR ROTARY | | | |
| _ | | • | | |
| | REVERSE | | | |
| OTHER (Specify) | | | | · |
| TOTAL DEPTH DRILLED | <u> </u> | | | |
| | | | _ | |
| CASING SEQUENCE | | | • | |
| | INNÉR OUTER | 1 | | |
| CASING TOP | /2 | | | |
| CASING BOTTOM 7 | 77 | | | |
| CASING DIAMETER | 4" | | | |
| | Prc | } | | |
| - | EN SEQUENCE | | | |
| SCRE | INNER JOUTER | | | |
| | 7 7 - OUTER | - | | |
| SCREEN TOP | | | | |
| SCREEN BOTTOM I——— | | DRILLERS LOG DESCRIPTION TO | OP OF STRATA | BOTTOM OF STRATA |
| SCREEN DIAMETER | 4' | | | |
| SCREEN MATERIAL | ν'C | | | |
| | WRITTEN APPROVAL FOR SCREENING/ GRAVEL PACKING MORE THAN ONE AQU- | TOP Soil | <i>a</i> | / |
| | IFER MUST BE OBTAINED FROM DNREC. | 707 3072 | | |
| GROUT TYPE: CEMENT FI | BENTONITE CLAY [CL | SILTY YELLOW SAND | / | 4 |
| GROUT TYPE: CEMENT BENTONITE CLAY OTHER: | | | eme H | 42 |
| FROM 40 TO 0 FEET | | FINE-CLARSE YELLOWS | 19100 7 | / ﴿ |
| | | FINE LUARSE ELEAN | | |
| NON-GROUT BACKFILL OF WELL ANNULUS | | | | |
| TYPE IVATIVE FROM 75 TO 40 FEET | | LiGHT YELLOGI SAINIS | 42 | 8.5 |
| GRAVEL PACK: TYPE MORIE | | 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - | . <u></u> | |
| FROM | | FINE-COARSE ORAN | 00 | |
| STATIC WATER LEVEL: DATE 10/20/92 | | SAND Y GRAGEL | 55 | タフ |
| FT. (Below, above) GR | | 7,,,,, | د. ر | |
| | | | | |
| PUMPING WATER LEVEL: 25 FT. BELOW GRADE | | | 1 | |
| AFTER $\frac{2}{}$ HOURS AT $\frac{90}{}$ GPM. | | | | |
| 14P1 1 1P45 001451 | ON. | 1 | | |
| WELL HEAD COMPLETI | - W (* / | SUPPLEMENTAL DRILLERS LOG | ATTACHED YE | S D NO L |
| TYPE: PITLESS ADAPTOR 🕰 | The state of the s | PAGE 1 OF PAGES | · 111 | |
| OTHER | | COMPANY NAME White Dulking | | |
| 12-INCHES ABOVE GRADE. | | SIGNATURE OF DRILLER IN CHA | ARGE 7 | DATE |
| The state of the s | | S. S | | , |
| 1 | | Queen that | 101 | 24/92_ |