

9-183
(October 1950)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Pd51-2

Pd51-2

LAW

WELL SCHEDULE

Date Sept. 27 15, 1959 Field No. Sub Hwy 27

Record by J. Coskery Office No. _____

Source of data Fld. Recon. (Well site)

1. Location: State Delaware County Sussex

Map SE corner junction US 13 & Rt 467A N of Laurel

Owner State Hwy Dept Address Dover, Del.

Tenant _____ Address _____

Driller Den. Hydro. Lab Address Denver, Colo.

3. Topography Coastal plain

4. Elevation 41 ft. above msl

Type: Dug, drilled, driven, bored, jetted drilled 9/15 59

6. Depth: Rept. _____ ft. Meas. 20.4 ft.

7. Casing: Diam. 1 in., to _____ in., Type _____

Depth _____ ft., Finish 3ft D.P. Screen

8. Chief Aquifer _____ From _____ ft. to _____ ft.

Others _____

9. Water level 5.95 ft. rept. 9-29 1959 above meas. below

had which is _____ ft. above below surface

10. Pump: Type _____ Capacity _____ G. M.

Power: Kind _____ Horsepower _____

11. Yield: Flow _____ G. M., Pump _____ G. M., Meas., Rept. Est., _____

Drawdown _____ ft. after _____ hours pumping _____ G. M.

12. Use: Dom., Stock, PS., RR., Ind., Irr., Obs. Hwy. Obs. well

Adequacy, permanence _____

13. Quality _____ Temp _____ °F.

Taste, odor, color _____ Sample Yes _____ No _____

Unfit for _____

14. Remarks: (Log, Analyses, etc.) Pumped small amount


of water, cleared.

Water table at 11 ft.

- 0 - 2 sand, F-M, some coarse, silty brown
- 2 - 7 Sand, M-C, silty light brown
- 7 - 11 Same
- 11-12 Sand, F-M, silty, tan
- 12-22 Sand, F-M, Silty, tan with black specks

Water table at 11 feet

22" T.D.



Pd51-2