

Pg 00-05

HBS
Alt. 35'

MAIL TO:
WATER SUPPLY BRANCH
DIVISION OF WATER RESOURCES
P.O. BOX 1401
DOVER, DELAWARE 19903

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
BE RETURNED WITHIN 30 DAYS
AFTER CONSTRUCTION DATE.

MONITOR / OBSERVATION WELL COMPLETION REPORT

PLEASE PRINT OR TYPE

PERMIT NO. 94658 LOCAL ID ob-10
 Owner Tomas Seeds Inc.
 Address P.O. Box 468
 City Millsboro State DE Zip 19966
 Telephone Number 302-934-3026
 Consulting Firm/Supervising Geologist (If applicable)
DNREC Blair Venable
 Telephone Number 302-739-4793
 Well Contractor Roland Bourds
 Date of Completion 4/6/93
 Name of DNREC Contact Person Blair Venable
 Drilling Method HAND Auger

IS COMPLETED WELL LOCATED AS SHOWN ON
APPLICATION FORM? YES [] NO []
IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

2.5L 1.35S 1.6M 7/94 JAM
g-p

WELL CONSTRUCTION
 Total depth drilled: 5.45'
 Depth to water 4.65' BGS (NOT NECESS)
 Surveyed Top of Casing Elevations at 1.1y
 Ft. above Sea Level Static

| DRILLERS LOG DESCIP. | TOP OF STRATA | BOTTOM |
|---|---------------|--------|
| pent | 0' | 0.2' |
| tan sandy loam (SL) | 0.2' | 1.1' |
| tan loamy sand (LS) | 1.1' | 1.6' |
| Variegated tan + orange sh 1.6' to 3.9' | | 3.9' |
| tan sandy loam (SL) water at 1.9' | | |
| at 2' pick up chrome 2 mattles and thin gravel layer | | |
| tanish LS | 3.9' | 4.1' |
| fine to coarse p sand with round sand sized CaCO3 at or the close partizles | 4.1' | ? |

.2L
.45L
.45M
.5L
1.15M
1.15L
.2L
1.35S

CASING SEQUENCE

| | Inner casing | Outer casing |
|-----------------|--------------|--------------|
| Casing top | 0.2' | |
| Casing bottom | 4.45' | |
| Casing diameter | 2" | |
| Casing material | PVC | |

SCREEN SEQUENCE

| | Inner casing | Outer casing |
|-----------------|--------------|--------------|
| Screen top | 4.45' | - |
| Screen bottom | 5.45' | |
| Screen diameter | 2" | |
| Screen material | PVC | |

Type of Grout Granular Britonite from 0 to 1.5'
 Gravel pack interval from 1.5' to 5.45'
 Aquifer/Formation screened in: Bever Dam Fm
 Type of samples (ditch, split spoon, etc.)
Auger Bites

Samples Logged By: Blair Venable
(Name)

Hydrologist DNREC
(Title) (Company)

Well Drilled By: Blair Venable DNREC
(Company Name)

Roland Bourds 5/10/93
(Signature of Driller in Charge) (Date)

SUPPLEMENTAL DRILLERS LOG ATTACHED?
YES [] NO []
PAGE 1 OF 1 PAGES

1993
WATER SUPPLY