PFS1-08 6

MAIL TO:

WATER SUPPLY SECTION
DIVISION OF WATER RESOURCES
89 KINGS HIGHWAY
DOVER, DELAWARE 19901
PHONE: 302-739-3665
FAX: 302-739-2296

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

PAGE _____ OF _____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 153995-W

LOCAL ID#

PROPERTY OWNER Jeff & Susan Cox

WELL CONTRACTOR Daisey's Well drilling

LIC# 13+994

DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0'	3'
sand & Clay	3'	32'
Tan sand	32'	56'
yellow sand	56'	63'
white & Tan sand & Gravel	63'	75'

OTHER COMMENTS:

RECEIVED
MAY 22 1998
WATER SUPPLY

I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Michael G. Daisey — Signature of Well Driller In Charge

13+994 — License#

10-1-97 — Date

White - DNREC • Canary - Contractor • Pink - Owner

Doc. No. 40-08-82-12-11