

Ph23-5

DESCRIPTIVE LOG

DGS No. Ph23-5      Drilling Method Auger      Date Drilled 7/10/80  
Local No. B-4      Project Aq Engineering      Logged by Bounds/DGS

Ditch Samples

Cores

<u>Depth</u>	<u>Lithology</u>	<u>Depth</u>	<u>Lithology</u>
0 - 2.5	Tan, Fine-Medium sand.		
2.5-4.5	Orange, fairly clayey medium-coarse sand with tr. gravel.		
4.5-5.5	Gray-blue, slightly silty clay.		
5.5-16.0	Yellowish tan, slightly medium sandy clay		
	(clay disappears with depth as grades into yellowish tan, medium sand)		
	(about 11.0' clay disappears).		

Water at 9'.

\*