

PH 43-09

BORING NO. RP#2

TRACT: 24-112-09 S.R. 24 - MAINLINE IMPROVEMENTS - RIVERSIDE PLAZA - MUSEUM SITE

BORING LOCATION:

PROGRESS NO.	DAILY SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/07/05 1	0.6'	2	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	7" Topsoil
	2.0'	3			
23" Recovery					
2	2.0'	3	Wet loose brown fine sand w/some coarse sand and clay.	A-2-4 (0)	
		4			
		6			
	4.0'	8			
20" Recovery					
3	4.0'	3	Wet medium dense brown silty fine sand w/some coarse sand.	A-2-4 (0)	Water @ 5.5'
		7			
		16			
	6.0'	12			
22" Recovery					
4	6.0'	12	Wet medium dense brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
		12			
		10			
	8.0'	12			
22" Recovery					
5	8.0'	7	Saturated dense brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
		16			
		22			
	10.0'	28			
20" Recovery					
6	13.0'	8	Wet medium dense brown coarse to fine sand w/some gravel and silt.	A-1-b (0)	
		10			
		10			
	15.0'	11			
( END )					

BORING NO. RP#2  
SURFACE ELEV.