

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

S.R.24 - MAINLINE IMPROVEMENTS - RIVERSIDE PLAZA - MUSEUM SITE
DM3-11

BORING NO. RP#4

CONTRACT: 24-112-09
BORING LOCATION:

DAILY PROGRESS NO.	SAMPLE DEPTH	BLOWS/5"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/08/05 1	0.5'	2	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	6" Topsoil
	2.0'	3			
		3			
22" Recovery					
2	2.0'	2	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
		2			
		3			
	4.0'	2			
20" Recovery					
3	4.0'	4	Saturated loose brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	Water @ 4.2'
		3			
		2			
	6.0'	2			
16" Recovery					
4	6.0'	2	Saturated loose brown fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
		3			
		3			
	8.0'	3			
20" Recovery					
5	8.0'	2	Saturated very loose brown fine sand w/some coarse sand and silt, trace of gravel.	A-2-4 (0)	
		2			
		2			
	10.0'	2			
20" Recovery					
6	13.0'	8	Saturated medium dense brown fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
		7			
		6			
	15.0'	6			
22" Recovery					
(END)					

BORING NO. RP#4
SURFACE ELEV.