

269
57

P. 21-1 AH II

DRILLERS LOG

THICKNESS OF STRATUM

DEPTH TO BOTTOM OF STRATUM

Tan Sand

0

8

Sandy Clay

8

38

Changed to Coarse Tan Sand

38

80

RECEIVED

APR 30 1984

WATER SUPPLY