

MONITOR / OBSERVATION WELL COMPLETION REPORT

Pg 11-00

PLEASE PRINT OR TYPE

PERMIT No 93254 LOCAL ID # 1
Owner Parker Block
Address Rt 24 West
City Millsboro State DE Zip 19966
Telephone Number _____
Consulting Firm/Supervising Geologist (If applicable)
Enviro Comp Services/Craig Magnus
Telephone Number 607-8010
Well Contractor A.C. Schultes of DE, Inc.
Date of Completion 11/21/92
Name of DNREC Contact Person _____
Drilling Method Auger

WELL CONSTRUCTION

Total depth drilled: _____
Depth to water NM
Surveyed Top of Casing Elevations
Inner _____ Ft. above Sea Level
Outer _____

CASING SEQUENCE

	Inner casing	Outer casing
Casing top	<u>0'</u>	
Casing bottom	<u>4'</u>	
Casing diameter	<u>4"</u>	
Casing material	<u>PVC</u>	

SCREEN SEQUENCE


	Inner casing	Outer casing
Screen top	<u>4"</u>	
Screen bottom	<u>19"</u>	
Screen diameter	<u>4"</u>	
Screen material	<u>PVC</u>	

Type of Grout Cement from 0 to 3
Gravel pack interval from _____ to _____
Aquifer/Formation screened in: Colombia
Type of samples (ditch, split spoon, etc.)
split spoons

Samples Logged By: Craig Magnus
Enviro Comp Services (Company)
(Title) _____

Well Drilled By: A.C. Schultes of DE, Inc.
Estela C. Orsola (Signature of Driller in Charge) _____
(Company Name) _____ (Date) _____

IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM? YES [] NO []
IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.



DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
<u>Backtopfrusher Run</u>	<u>0</u>	<u>2</u>
<u>Tan Sand+Silt</u>	<u>2</u>	<u>4</u>
<u>Tan+Gray Clay</u>	<u>4</u>	<u>9</u>
<u>Orange Sand</u>	<u>9</u>	<u>19</u>

SUPPLEMENTAL DRILLERS LOG ATTACHED?
YES [] NO []
PAGE 1 OF 1 PAGES