

WATER SUPPLY BRANCH  
 DIVISION OF ENVIRONMENTAL CONTROL  
 P.O. BOX 100  
 COVEN, DELAWARE 19803

WELL COMPLETION REPORT

WATER SUPPLY BRANCH  
 DIVISION OF ENVIRONMENTAL CONTROL  
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT AND ENVIRONMENTAL CONTROL

PLUMIT NO. 19921 LOC 4, D Y-7

OWNER Phase 2-2's

INSTALLATION DATE 11-23-87  Permanent

PURPOSE:  TEST

USE:  DOMESTIC  ABSOLUTE PUMP  NO

COMMERCIAL  INDUSTRIAL

RESEARCH  PUBLIC

RECREATION  SEWERAGE

HEAT PUMP RECHARGE  HEAT PUMP SUPPLY

OTHER (Specify)

IS THIS A REPLACEMENT WELLY YES  NO

ABANDONMENT DATE FOR OLD WELL 01/27

ABANDONMENT METHOD APPROXIMATELY 200 FEET

DRILLING METHOD

AUGERED  SOLED  CABLE TOOL

DRIVEN  JETTED  AIR ROTARY

WILD ROTARY  REVERSE  WASHED

OTHER (Specify)

TOTAL DEPTH DRILLED 44.0

CASING SEQUENCE

DEPTH	TYPE	REMARKS
-2.0		
-29.0		
4	PVC	

SCREEN SEQUENCE

DEPTH	TYPE	REMARKS
-40.0		
	PVC	

SCREEN MATERIAL

SC IN TOP

SCREEN BOTTOM

SCREEN DIAMETER

SCREEN MATERIAL

GROUT TYPE CEMENT  PORTLAND CLAY

OTHER

FROM 14 TO 0 FEET

NON-CESST BACKFILL OF WELL ANNULUS

TYPE FROM TO FEET

GRAVEL PACK TYPE CRAGG #2

FROM 45 TO 19 FEET

STATIC WATER LEVEL DATE 11-25-87

19.25 FT (Below ground surface)

PUMPING WATER LEVEL 21.5 FT BELOW GRADE

AFTER 17 HOURS AT 2.5 GPM

WELL HEAD COMPLETION:

TYPE PATENT ADAPTOR

OTHER

INCHES ABOVE GRADE

TYPE OF PERMANENT PUMP INSTALLED:

PUMP MANUFACTURE

DATED CAPACITY (GPM)

PUMP INTAKE SETTINGS

THIS COMPLETED WELL IS

YES NO

A. AT LEAST 15' FROM ANY FOUNDATION

B. AT LEAST 80' FROM ANY SEPTIC TANK

C. AT LEAST 10' FROM TOWN WATER LINE

D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TIE FIELD

THE NEAREST NEIGHBORS (CIRCLE ONE):

SEPTIC TILE FIELD CAMPPOOL OR PRIVY

IS FROM COMPLETED WELL

IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM?

IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS

36 RJ

FEB 17 1988

WATER SUPPLY

DRILLERS LOG DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
BEANSE SANDY/CLAY	0	7.0
Thin SANDY/CLAY	7.0	12.0
GRAVEL SAND	12.0	18.0
CLAYEY SAND	18.0	20.0
TAN COB SAND	20.0	21.0
CLAY COB SAND	21.0	27.0
BEANSE SAND (COB)	27.0	44.0

SUPPLEMENTAL DRILLERS LOG ATTACHED YES  NO

PAGE 1 OF 1 PAGES

COMPANY NAME SANTA BATA, INC.

SIGNATURE OF DRILLER IN CHARGE Tucker Thorland DATE 12-7-87

WHITE - DRILLS CONTRACTOR

CANNAY - CONTRACTOR

PINK - OWNER