

MAIL TO:  
 WATER SUPPLY BRANCH  
 DIVISION OF WATER RESOURCES  
 P.O. BOX 1401  
 DOVER, DELAWARE 19903

STATE OF DELAWARE  
 DEPARTMENT OF NATURAL RESOURCES  
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST  
 BE RETURNED WITHIN 30 DAYS  
 AFTER CONSTRUCTION DATE.

MONITOR WELL COMPLETION REPORT

02914-71

PLEASE PRINT OR TYPE  
 PERMIT NO. 7744 LOCAL ID W 378  
 Owner MAR MITCHELL BOBRO  
 Address 499 MITCHELL STR.  
 City MILLSBORO State DEL Zip 19966  
 Telephone Number 703-821-3700  
 Consulting Firm/Supervising Geologist (If applicable)  
ENVIRON. STRATEGIES CORP./DIANE KINDIG  
 Telephone Number 703-821-3700  
 Well Contractor DELMARVA DRILLING CO.  
 Date of Completion 3/3/89  
 Name of DNREC Contact Person DIANE WEHNER  
 Drilling Method Mud rotary

WELL CONSTRUCTION

Total depth drilled: 70'  
 Depth to water 14' 2"  
 Surveyed Top of Casing Elevations  
N/A N/A Ft. above Sea Level  
Inner Outer

CASING SEQUENCE

Inner casing	Outer casing
<u>51'</u>	
<u>50'</u>	
<u>4"</u>	
<u>PVC</u>	

SCREEN SEQUENCE

Inner casing	Outer casing
<u>50'</u>	
<u>60'</u>	
<u>4"</u>	
<u>PVC</u>	

Type of Grout CEMENT from 0 to 42  
 Gravel pack interval from 48 to 60  
 Aquifer/Formation screened in: COLOMBIA  
 Type of samples (ditch, split spoon, etc.)  
SPLIT SPOON

Samples Logged By: LISA BRYOLA  
(Name)  
GEOLOGIST / ENVIRON. STRATEGIES CORP  
(Title) (Company)

Well Drilled By: DELMARVA Drilling Co.  
(Company Name)  
Kenneth P. DeRubele 3/3/89  
(Signature of Driller in Charge) (Date)

IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM? YES  NO

IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
<u>TOP SOIL</u>	<u>0</u>	<u>1</u>
<u>Med to coarse TAN SAND</u>	<u>1</u>	<u>7</u>
<u>Med to coarse TAN SAND w/ GRAVEL</u>	<u>7</u>	<u>42</u>
<u>Med to coarse TAN SAND w/ GRAVEL</u>	<u>42</u>	<u>65</u>
<u>Med to coarse FINE GRAVEL</u>	<u>65</u>	<u>70</u>

RECEIVED  
 MAR 20 1989

SUPPLEMENTAL DRILLERS LOG ATTACHED?  
 YES  NO   
 PAGE 1 OF 1 PAGES