MAIL TO: WATER SUPPLY BRANCH DIVISION OF WATER RESOURCES P.O. BOX 1401 DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED 30 DAYS AFTER CONSTRUCTION DATE

MONITOR WELL COMPLETION REPORT

PLEASE PRINT OR TYPE	<i>1</i> 6.
PERMIT NO. 789 3.2 LOCAL ID P-6	IS COMPLETED WELL LOCATED AS SHOWN ON
Owner Adisbere Frank Fred Santony Sun A	. <i>/</i> · –
Address, Box 579	IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.
City Fran State De Zip 18947	, , , , , , , , , , , , , , , , , , ,
Telephone Number	
Consulting Firm/Supervising Geologist (If applicable)	
George Miles + Buhr	·
Telephone Number 301 - 742 - 31/5	
Well Contractor Entire Utth Inc 1473	
Date of Completion 6/1/89	
Drilling Method: Hour fleiger	
	Qh21-1
WELL CONSTRUCTION Total depth drilled: (7)	,
Total depth drilled:	DRILLERS LOG DESCRIP. TOP OF STRATA BOTTOM
Surveyed Top of Casing Elevations	Al-
Ft. above Sea Level	flet TO Course ent 0 10
Inner Outer	
CASING SEQUENCE	
Inner casing Outer casing	
Casing top + 3	
Casing diameter 3/4"	
Casing diameter Casing material	
SCREEN SEQUENCE	
Inner casing Outer casing	
Screen top -8	
Screen bottom -IC	
Screen diameter 3/4"	
Screen material	
0 . 4	
Type of Grout Contact from 0 to -7	
Gravel pack interval from 7 to -10	
Aquifer/Formation screened in: Colum h. it	
	IN E G ENT COLUMN
Samples Logged By: T. King	
(Name)	WATER QUESTION
I ledon de la Catalana	
(Tale) (Campany)	
1	
[LO + 1 = /1122	
Well Drilled By: Couth Cotta Inc /473	
// ~ 10	
	SUPPLEMENTAL DRILLERS LOG ATTACHED?
1/1 mas Muller 1/3 1.2.90	YES[] NO[]
(Date)	PAGE 1 OF PAGES