MAIL TO:

WATER SUPPLY SECTION **DIVISION OF WATER RESOURCES** 89 KINGS HIGHWAY DOVER, DELAWARE 19901 PHONE: 302-739-3665 FAX: 302-739-2296

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

4 70 "

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

0h21-29	PAGE	OF	PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL B	E RETURNED			
PERMIT# 153816-W	LOCAL ID#			
PROPERTY OWNER PAUL BRASURE				
WELL CONTRACTOR Daisey's Well Drilling DESCRIPTION	LIC# /3 	LIC# 13 + 994		
	TOP OF STRATA	BOTTOM OF STRATA		
Top Soil Clay + Sand Sand yellow sand Tan gand + Gravel	0′	3′		
Clay + Sand	3′	17'		
5and	17'	38'		
yellow sand	38′	<i>5</i> 3′		
Tan sand + Gravel	<i>5</i> 3 '	70'		
·				
	DEGE	OVE		
		2 1998		
	— MAY 2			
OTHER COMMENTS:	WATER	SUPPLY		
7				
I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT				
Michael G. Daises		27-97		
Signature of Well Driller In Charge	License# Date			