

12-7.
 Q: ~~W-10~~ P51 Frankford Quadrangle August ²⁴ ~~20~~, 1988
 Test Hole drilled at Paul Justice borrow pit; Elev. 8'
 West of RT 348 (0.4 mi), south of road to Blackwater
 Beach

Depth 0-5 Sand; m-f; cly to silty cly; silty; dk brn @ surf.
 grades down to cream. some crs.

⁴⁴
~~5-44~~ Sand; crs. cream-wh; silty; silty cly; scat
 sml pbl. siltier from 30-44 - color darkens
 to lt rdsh brn

44-156 Sand; crs - v crs. cream-tan; gravel layers
 at 65', 88-89; silty, clayey zone at 92-93.5
 clay at 122-126 ft;

156-159 Clay; dk brn; silty; v sticky;

159-169 Silt? or Sand; silty, cly.

