## DESCRITIVE LOG FOR WELL Qil5-3 Bayshore Mobile Home Park, Ocean View, DE

0-2	Fill and top soil
2-4	clayey black and gray subsoil
4-9	slightly clayey yellow-tan sand
9-12	fine and coarse dirty white sand
12-14	fine and coarse dirty yellow sand
14-26	fine to coarse very dirty white sand and pieces of clay
26-32	silty yellow and orange clay
32-37	light gray clay
37-39	orange clay
39-42	very fine to very coarse yellow sand
42-71	very fine to very coarse yellowish-white sand and some
	small gravel, dirty, with pieces of silty white clay
71-77	very fine to very coarse yellow sand (mostly medium to coarse)
	and small gravel.
77-81	very fine to very coarse white and light yellow sand
03 05	(mostly coarse) and small gravel
81-87	very fine to very coarse orange sand (mostly coarse) and
	small gravel
87-90	very fine to very coarse yellow sand and small gravel
90-106	very fine to coarse light yellow sand and silt
106-114	very fine to some coarse yellowish-white sand
114-130	silty gray clay with wood
130-152	clayey, very fine, and fine gray sand and silt
152-165	very fine and fine light gray sand
165-178	very fine to coarse light gray sand (mostly fine)
178-194	same, less coarse sand
194-202	same, with very coarse sand

T. D. 202' Descriptive log by Roy White, driller

Please note that the final production well was drilled in this test well to a depth of 170'