Boring No.: PB#36

Ft.

Ft.

STATE OF DELAWARE **DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS**

F.A. Project: S.R. 26, Atlantic Avenue from Clarksville to Assawoman Canal

Contract: 24-112-10

Boring Location: Sta. 67+60, 130' Lt. C.L.

Boring Surface Elev.: + 16.0'

Wt. of Casing Hammer:
Wt. of Sample Hammer: 140
Type of: D-Sampler: S-Sampler:
U-Sampler: Average Fall: Average Fall: O.D. of Sampler: O.D. of Samp. Tube: O.D. of Samp. Tube: O.D. of Rock Core; Lbs. IX. IX. IX. IX. IX. Lbs. O.D. 30 Split-Barrel O.D. O.D. O.D. Core Bit:

From Depth of: From Depth of: Casing Size: 3 1/4" Inches 0.0'To: 18.0' Hollow Stem Auger:

Water Level Readings

Depth of Water 5.5' **Date** 5/4/2006 Time Depth of Hole **Depth of Casing** Elev. of Water 1:00 p.m. 6.0 4.0'

Pay Quantities: 2 1/2 in. Dia. Dry Sample Boring: No. of 2 in. Dia. Shelby Tubes: 2 1/2 in. Dia. Contin. Sample Boring: 20.0 Ft.; Dia. U-Sample Boring: No. of: U-Samples: Ft.; Core Drilling in Rock:

Boring Contractor: Walton Corporation Driller: Dave Burt

Helpers: Jim Deal & Wayne Hurd

Q: 23-28

Reference: Survey

| Depth (ft.) | Daily Progress | No. | Sample Depth | Blows/6" | Sample Description Class | ./G.I. Remarks |
|----------------|-------------------|-----|-----------------|------------------|--|----------------|
| 3 | | 1 | 2.0' | 3 8 7 6 | Moist medium dense brown silty fine sand A-2- w/trace of coarse sand and gravel. | 4(0) |
| | | 2 | 4.0' 4.0' | 5 5 4 3 | 22" RECOVERY Wet loose brown silty fine sand w/some A-2- coarse sand, trace of gravel. | 4(0) |
| 6 | | 3 | 6.0' | 1 1 2 2 | 2* RECOVERY Saturated very loose brown silty fine sand A-2- w/some coarse sand, trace of gravel. | 4(0) |
| 9 | | 4 | 8.0' 8.0' | 2 4 2 5 | 22" RECOVERY Saturated loose brown silty fine to coarse sand w/trace of gravel. 22" RECOVERY | 4(0) |
| 12 | | 5 | 10.0' | 1 2 1 3 | Saturated very loose brown silty fine sand A-2-w/trace of coarse sand and gravel. 24" RECOVERY | 4(0) |
| | | 6 | 12.0' | 2 3 4 8 | Saturated loose brown fine to coarse sand A-2-w/some silt, trace of gravel. 22" RECOVERY | 4(0) |
| 15 | | 7 | 14.0' | 2 2 1 2 | Saturated very loose brown silty fine sand A-2- w/some coarse sand, trace of gravel. 24" RECOVERY | 4(0) |
| 18 | | 8 | 16.0' 18.0' | 2 2 4 2 | Saturated loose brown fine to coarse sand A-2-w/some silt, trace of gravel. 24" RECOVERY | 4(0) |

Remarks:

| Reviewed By: | Soils Supervisor: |
|--------------|-------------------|
| | |

STATE OF DELAWARE DEPARTMENT OF TRANSPORTATION **DIVISION OF HIGHWAYS**

F.A. Project: S.R. 26, Atlantic Avenue from Clarksville to Assawoman Canal

Contract: 24-112-10

٠,٠

Boring No.: PB#36

| Depth | apth Daily Sample | | | | | | | |
|-------|-------------------|-----|--------------------------|------------------|---|-------------|---------|--|
| (ft.) | Daily Progress | No. | Sample Depth 18.0' | Blows/6" | , | Class./G,I, | Remarks | |
| | | 9 | 18.0° | 1 2 4 5 | Saturated loose brown fine sand w/some silt and coarse sand, trace of gravel. | A-2-4(0) | | |
| 21 | | 10 | 20.0 | 3 4 4 3 | Saturated loose brown fine to coarse sand w/some silt, trace of gravel. | A-2-4(0) | | |
| | | | 22.0 | | 24" RECOVERY | | | |
| 24 | | | | | | | | |
| 27 | | | | | | | | |
| | | | | | | | | |
| 30 | | | | | | | | |
| 33 | | | | | | | | |
| | | | | | | | | |
| 36 | | | | | | | | |
| | | | | | | | | |
| 39 | | | | | | | | |
| 42 | | | | | | | | |
| | | | | | | | | |
| 45 | | | | | | | | |

KEY TO SYMBOLS

| | _ | | | |
|--------|-------|---|------|----|
| Symbol | Desci | 2 | otı. | ממ |
| ~ | | | | |

Strata symbols

Silty sand



Sand

Notes:

- 1. Exploratory borings were drilled on 5-4-2006 using a 3 1/4-inch diameter hollow stem auger.
- 2. No free water was encountered at the time of drilling or when re-checked the following day, unless recorded on 1st page.
- 3. Boring locations were taped from existing features and elevations extrapolated from survey unless otherwise reported.
- 1. These logs are subject to the limitations, conclusions, and recommendations in this report.
- 5. Results of tests conducted on samples recovered are reported on the logs.