MAIL TO:

WATER SUPPLY SECTION DIVISION OF WATER RESOURCES 89 KINGS HIGHWAY DOVER, DELAWARE 19901

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

http://www.dnrec.state.de.us/

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION. A WELL FORMATION LOG MUST BE INCLUDED WITH THIS REPORT.

PHONE: 302-739-9944 WELL COMPLETION REPORT		-Authorization Number-
FAX: 302-739-7764		
ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED		
PLEASE PRINT OR TYPE - USE BLUE OR BLACK INK ONLY	WELL C	CONSTRUCTION METHOD
Permit #: 221106 Local ID:		
Tax Map/Parcei #: 1-34-17-26.02	O Augered O Driven	o Bored o Cable Tool
Property Owner: BMA	Mud Rotary	o Jetted o Air Rotary o Reverse o Washed
	o Other (Specify):	
	Total Depth of Excavation:	00
Well Driller in Charge during Construction: 5-6144	Construction Date: 10/30	107
CASING INSTALL ATTOM		
CASING INSTALLATION: INNER CASING	SCREEN INSTALLAT	ION
CASING TOP: /1	CORPELEN	90
CASING BOTTOM: 90	SCREEN TOP:	70
CASING DIAMETER:	SCREEN BOTTOM:	100 PVC
CASING MATERIAL:	SCREEN DIAMETER:	
702	SCREEN MATERIAL:	avc_
OUTER CASING	COPERI OF OFFI	7//
(1) (2) (3)	SCREEN SLOT SIZE	7THOUSANDS
CASING TOP:	Ch 11/21 h	
CASING BOTTOM:	GRAVEL PACK SIZE	
CASING DIAMETER:		
CASING MATERIAL:		
Gravel Pack From: 90 ft. To: 100	Site Plan - Include lot size and	dimensions, distances from well to house, property
Grout Type: o Cement Bentonite Clay	lines, nearest road, and all neart	by septic systems (include suitable plot plan if
o Other: From: ft. To: ft.	available). (If different from o	Priginal annication)
Type of Non-Grout backfill of Well Annulus:		a
From: 40 To: 90		
Static Water Level: 13 A. Below OR o Above Ground Surface		
On (date): 10 130 Below OR o Above Ground Surface		
Pumping Water Level: 7		
Pumping Water Level: 7 ft. On (date): 10/30/07 After: hrs. Pumping		
Was a Geophysical hrs. Pumping at: 25		
UPM		
WELL HEAD COMPLETION: Type: Adapter		
O Standard "T"		
o Well Pit o Pad Mount		
O Other - Specify:		
Well Head Completed: / inches bove (OR) o Below Ground Surface Was the Well Tag attached in country.		
Was the Well Tag attached in accordance with current regulations?	LUEDRAN	
YES ONO If "NO", Please Explain:	ACCURATE AND CORRECT	NPORMATION I HAVE SUBMITTED IS
, roase Explain:	The colder	
	Signature - Well Driller in C	
	4129	1 1
	License #	10/30/07

MAIL TO:

WATER SUPPLY SECTION DIVISION OF WATER RESOURCES 89 KINGS HIGHWAY DOVER DELAWARE 19901

PHONE: 302-739-9944 FAX: 302-739-7764

STATE OF DELAWARE **DEPARTMENT OF NATURAL RESOURCES** AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

	PAGE	OFPAG		
TE FORMS WILL BE RETURNED				
T LOCAL ID#				
	1 5.	^		
DESCRIPTION		TOP OF STRATA BOTTOM OF		
	TOT OF STRATA	STRATA		
Topsoil	0	1		
Sound		15		
day+ shell	15	70		
chy & Sans	70	85		
LOANE SONO	85	100		
		-		
	<u> </u>			
JBMITTED IS ACCURATE AND CO)DDFor			
	Topsoil Sons Clay & Sons Coarle Sons	ILICAL IDA LICA 7/ TOP OF STRATA TOP SOIL SOLL SOLL Chy & Soll Chy & Soll Const. Soll S		