



HANDEX CORP., 360 Morgan Road, P.O. Box 522, Odenton, Maryland 21113 (301) 674-3100

DRING LOG

Application No. 65044 Permit No. 65044E
 Drilled 05-17-86 County Sussex Use monitor
 Location NW corner of US 1 and York Rd., South Bethany, Delaware
 Driller Service Oil Co. Address PO Box 279, Milford, Del. 19963
 Drilling Method Air Rotary Sampling Method cuttings
 Hole Diameter 7" Total Depth 11'
 Casing: Type PVC (no glue) Diameter 4" Length 5'
 Screen: Type PVC (no glue) Slot 20 Diameter 4" Length 10.5'
 Gravel Pack Size none Casing Seal cement
 Static Water Level 3.10' BTOC Geologic Formation Sand

DEPTH BELOW SURFACE	SAMPLE NUMBER	GLOWS PER 6" ON SAMPLER	WELL DESIGN	IDENTIFICATION OF SOILS/REMARKS
0.5'			well screen	Gravel and asphalt and sand fill
2'				White, medium, very well sorted, subrounded quartz, SAND
				Tan to brown, medium, very well sorted, subrounded, quartz, SAND
6'				Gray, medium, very well sorted, subrounded, quartz SAND
11'				note: all wells completed below grade in a manhole with seal and locking cap.
				Log by S. Boyes
				Q: 52-49