

MAIL TO:
 WATER SUPPLY SECTION
 DIVISION OF WATER RESOURCES
 P.O. BOX 1401, 89 KINGS HIGHWAY
 DOVER, DELAWARE 19903
 PHONE: 302-739-3665
 FAX: 302-739-2296

STATE OF DELAWARE
 DEPARTMENT OF NATURAL RESOURCES
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
 BE RETURNED WITHIN 30 DAYS OF
 CONSTRUCTION DATE

FORMATION LOG

Rd 31-19

PAGE 2 OF 2 PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 163391	LOCAL ID#	
PROPERTY OWNER Delmar Delabell District		
WELL CONTRACTOR Richard Window	LIC# 1029	
DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0	
Tan Clay	1	10
White & Tan Sand	10	55
Coarse Tan Sand	55	100
Blue Clay	100	115
Blue Clay (Shell) & Sand	115	160
Tan Sand	160	250
Blue Clay & Shell	250	304
- not very good log		deep

OTHER COMMENTS:

RECEIVED

MAY 02 2003

WATER SUPPLY

I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Signature of Well Driller In Charge: *Richard Window* License# 1029 Date 10-1-99

White - DNREC • Canary - Contractor • Pink - Owner Doc. No. 40-08-82-12