

**STATE OF DELAWARE  
DEPARTMENT OF NATURAL RESOURCES  
AND ENVIRONMENTAL CONTROL**

WELL COMPLETION REPORT MUST  
BE RETURNED 30 DAYS AFTER  
CONSTRUCTION DATE

APPLY BRANCH  
OF ENVIRONMENTAL CONTROL  
BOX 1401  
DOVER, DELAWARE 19903

*(Connection)*

**WELL COMPLETION REPORT**

PLEASE PRINT

PERMIT NO. 91259 LOCAL ID \_\_\_\_\_

OWNER William Freeman

CONSTRUCTION DATE June 15, 1992  
PURPOSE:  TEST  PERMANENT

USE:  DOMESTIC  AGRICULTURAL  
 COMMERCIAL  INDUSTRIAL  
 IRRIGATION  PUBLIC  
 MONITOR  DEWATERING  
 HEAT PUMP RECHARGE  HEAT PUMP SUPPLY  
 OTHER (Specify) \_\_\_\_\_

IS THIS A REPLACEMENT WELL? YES  NO   
ABANDONMENT DATE FOR OLD WELL \_\_\_\_\_  
ABANDONMENT METHOD \_\_\_\_\_

**DRILLING METHOD**

AUGERED  BORED  CABLE TOOL  
 DRIVEN  JETTED  AIR ROTARY  
 MUD ROTARY  REVERSE  WASHED  
 OTHER (Specify) \_\_\_\_\_  
TOTAL DEPTH DRILLED 60

**CASING SEQUENCE**

INNER	OUTER
+1	
53	
4	
PVC	

**SCREEN SEQUENCE**

INNER	OUTER
53	
60	
4	
PVC	

WRITTEN APPROVAL FOR SCREENING/  
GRAVEL PACKING MORE THAN ONE AQUIFER  
MUST BE OBTAINED FROM DNREC.

GROUT TYPE: CEMENT  BENTONITE CLAY   
OTHER: \_\_\_\_\_  
FROM 0 TO 53 FEET  
NON-GROUT BACKFILL OF WELL ANNULUS  
TYPE None FROM \_\_\_\_\_ TO \_\_\_\_\_ FEET  
GRAVEL PACK: TYPE Grit  
FROM 53 TO 60 FEET  
STATIC WATER LEVEL: DATE 6-15-92  
5 FT. (Below, above) GROUND SURFACE  
PUMPING WATER LEVEL: 70 FT. BELOW GRADE  
AFTER 5 HOURS AT 35 GPM.

**L HEAD COMPLETION**

TYPE: PITLESS ADAPTOR   
OTHER  \_\_\_\_\_  
8 INCHES ABOVE GRADE.

**TYPE OF PERMANENT PUMP INSTALLED:**

PUMP MANUFACTURE \_\_\_\_\_  
RATED CAPACITY (GPM) \_\_\_\_\_  
PUMP INTAKE SETTING \_\_\_\_\_ FT. BELOW GRADE


**THE COMPLETED WELL IS?**

	YES	NO
A. AT LEAST 15' FROM ANY FOUNDATION	<input type="checkbox"/>	<input type="checkbox"/>
B. AT LEAST 50' FROM ANY SEPTIC TANK	<input type="checkbox"/>	<input type="checkbox"/>
C. AT LEAST 10' FROM TOWN SEWER LINE	<input type="checkbox"/>	<input type="checkbox"/>
D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TILE FIELD	<input type="checkbox"/>	<input type="checkbox"/>

**THE NEAREST NEIGHBORS (CIRCLE ONE)**

SEPTIC TILE FIELD CESSPOOL OR PRIVY  
IS 40 FROM COMPLETED WELL.  
IS COMPLETED WELL LOCATED AS SHOWN  
ON APPLICATION FORM?    
IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

*Re 12-11 Tina Dr*



DRILLERS LOG DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0	2
Tan Sand	2	10
Tan clay	10	13
Dark tan sd	13	40
Coarse tan sd	40	60

SUPPLEMENTAL DRILLERS LOG ATTACHED YES  NO   
PAGE 1 OF 2 PAGES  
COMPANY NAME Lifetime Well Drilling  
SIGNATURE OF DRILLER IN CHARGE: \_\_\_\_\_ DATE \_\_\_\_\_