

WELL COMPLETION REPORT

NO 69962 LOCAL ID 731  
Clifton Cordrey

CONSTRUCTION DATE 07-14-87  
TYPE:  TEST  PERMANENT

- DOMESTIC  AGRICULTURAL  
 COMMERCIAL  INDUSTRIAL  
 IRRIGATION  PUBLIC  
 MONITOR  DEWATERING  
 HEAT PUMP RECHARGE  HEAT PUMP SUPPLY  
 OTHER (Specify) \_\_\_\_\_

IS A REPLACEMENT WELL? YES  NO   
 INSTALLMENT DATE FOR OLD WELL \_\_\_\_\_  
 INSTALLMENT METHOD \_\_\_\_\_

DRILLING METHOD

- CORED  BORED  CABLE TOOL  
 OPEN  JETTED  AIR ROTARY  
 AIR ROTARY  REVERSE  WASHED  
 OTHER (Specify) \_\_\_\_\_  
 DEPTH DRILLED 60

CASING SEQUENCE

	INNER	OUTER
TOP	<u>1</u>	
BOTTOM	<u>30</u>	
DIAMETER	<u>4</u>	
MATERIAL	<u>PVC</u>	

SCREEN SEQUENCE

	INNER	OUTER
TOP	<u>30</u>	
BOTTOM	<u>60</u>	
DIAMETER	<u>4</u>	
MATERIAL	<u>PVC</u>	

WRITTEN APPROVAL FOR SCREENING/  
GRAVEL PACKING MORE THAN ONE AQUIFER  
MUST BE OBTAINED FROM DNREC.

TYPE: CEMENT  BENTONITE CLAY

3 TO 40 FEET  
 JOINT BACKFILL OF WELL ANNULUS  
water clay FROM 40 TO 60 FEET  
 PACK: TYPE grit  
40 TO 60 FEET  
 WATER LEVEL: DATE 07-14-87  
 (Below/above) GROUND SURFACE  
 GROUND WATER LEVEL: 90 FT. BELOW GRADE  
5 HOURS AT 120 GPM.

HEAD COMPLETION:

WATERLESS ADAPTOR   
 \_\_\_\_\_  
 INCHES ABOVE GRADE.

TYPE OF PERMANENT PUMP INSTALLED:


PUMP MANUFACTURE \_\_\_\_\_  
 RATED CAPACITY (GPM) \_\_\_\_\_  
 PUMP INTAKE SETTING \_\_\_\_\_ FT. BELOW GRADE

THE COMPLETED WELL IS?

- YES NO  
 A. AT LEAST 5' FROM ANY OVERHANG    
 B. AT LEAST 50' FROM ANY SEPTIC TANK    
 C. AT LEAST 10' FROM TOWN SEWER LINE    
 D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TILE FIELD

THE NEAREST NEIGHBORS (CIRCLE ONE)

SEPTIC TILE FIELD GESSPOOL OR PRIVY  
 IS \_\_\_\_\_ FROM COMPLETED WELL.  
 IS COMPLETED WELL LOCATED AS SHOWN  
 ON APPLICATION FORM?    
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.



RECEIVED

AUG 10 1987  
 Re 21-03

WATER SUPPLY.

DELLERS LOG DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
<u>Topsoil</u>	<u>0</u>	<u>1</u> ✓
<u>Lean Sand</u>	<u>1</u>	<u>8</u> ✓
<u>Med Lean Sand</u>	<u>8</u>	<u>18</u> ✓
<u>Coarse Gravel</u>	<u>18</u>	<u>20</u> ✓
<u>Med to coarse Dark Sand</u>	<u>20</u>	<u>30</u> ✓
<u>Coarse light sand</u>	<u>30</u>	<u>60</u>

SUPPLEMENTAL DRILLERS LOG ATTACHED YES  NO

PAGE 1 OF 1 PAGES  
 COMPANY NAME Hi-Tone Well Drilling Co  
 SIGNATURE OF DRILLER IN CHARGE: \_\_\_\_\_ DATE \_\_\_\_\_