

WELL COMPLETION REPORT

86879 TYPE OF PERMANENT PUMP INSTALLED:

LOCAL ID _____
 DATE OCT 2, 1986
 OPERATOR Walter D. Curry Jr.

DATE OCT 2, 1986
 TEST PERMANENT
 DOMESTIC AGRICULTURAL
 COMMERCIAL INDUSTRIAL
 IRRIGATION PUBLIC
 SPRINKLER DEWATERING
 RECHARGE HEAT PUMP SUPPLY

PLACEMENT WELL? YES NO
 DATE FOR OLD WELL NO
 METHOD CEMENT NEW WELL
OCT. 3, 1986

DRILLING METHOD
 BORED CABLE TOOL
 JETTED AIR ROTARY
 REVERSE WASHED
 DRILLED 101

CASING SEQUENCE

8.5"	OUTER
5.5"	
2"	
PVC	

SCREEN SEQUENCE

5.5"	OUTER
101	
2"	
PVC	

WRITTEN APPROVAL FOR SCREENING
 CHANGED SCREEN MORE THAN ONE FOOT
 MUST BE OBTAINED FROM OWNER.

CEMENT BENTONITE CLAY
 TO _____ FEET
 BACKFILL OF WELL ANNULUS
 FROM 5' TO 55' FEET
 TYPE 3/4"
 TO 101 FEET
 LEVEL DATE OCT 2, 86
 (BY OWNER) GROUND SURFACE
 DEPTH: 25' FT. BELOW GRADE
 HOURS AT 35 GPM.

COMPLETION:
 ABOVE GRADE
 BELOW GRADE

PUMP MANUFACTURER _____
 RATED CAPACITY (GPM) _____
 PUMP INTAKE SETTING _____ FT. BELOW GRADE
 THE COMPLETED WELL IS? YES YES NO
 A. AT LEAST 5' FROM ANY OVERHANG
 B. AT LEAST 50' FROM ANY SEPTIC TANK
 C. AT LEAST 10' FROM TOWN SEWER LINE
 D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TILE FIELD

THE NEAREST NEIGHBORS (CIRCLE ONE)
 SEPTIC (TILE FIELD) CESSPOOL OR PRIVY
 IS 300' FROM COMPLETED WELL
 IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM?
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

RECEIVED
 OCT 5 1986
 WATER SUPPLY
 RWS-08

DRILLERS LOG DESCRIPTION TOP OF STRATA BOTTOM OF STRATA

TOP SOIL	0	6"
SILTY TILL SAND	6"	3'
FINE TO MEDIUM YELLOW SAND	3'	9'
FINE GRAY SANDY MUD	9'	21'
SILTY GRAY SAND		
CLAY MUD	21'	52'
VERY FINE TO COARSE GRAY SAND	52'	61'

SUPPLEMENTAL DRILLERS LOG ATTACHED YES NO
 PAGE 1 OF _____ PAGES
 COMPANY NAME W.D. Curry Jr.
 SIGNATURE OF DRILLER IN CHARGE Walter D. Curry Jr. DATE OCT 6, 86