

STATE OF DELAWARE  
 DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 4

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS  
 BORING LOCATION: STA. 1020+09, 32.9' Lt. CENTERLINE

R124-54

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
1/6/05	1	1.0' 2.0'		Wet brownish gray silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
16" Recovery						
	2	2.0' 4.0'		Saturated brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
21" Recovery						
	3	4.0' 6.0'		Saturated gray coarse to fine sand w/trace of gravel and silt.	A-1-b (0)	
24" Recovery						
	4	6.0' 8.0'		Saturated gray coarse to fine sand w/trace of gravel and silt.	A-1-b (0)	
24" Recovery						
( END )						

BORING NO. S # 4  
 SURFACE ELEV. + 3.71'

No blow counts boring done with geoprobe