

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 8

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
BORING LOCATION: STA. 1040+27, 25' Lt. CENTERLINE

R:24-60

| DAILY PROGRESS | NO. | SAMPLE DEPTH | BLOWS/6" | SAMPLE DESCRIPTION | CLASS/G.I. | REMARKS |
|-------------------|-----|-----------------|----------|---|------------|---------|
| 1/4/05 | 1 | 1.0' 2.0' | | Wet brown silty fine sand w/some coarse sand. | A-2-4 (0) | |
| 21" Recovery | | | | | | |
| | 2 | 2.0' 4.0' | | Wet brown fine to coarse sand w/some silt. | A-2-4 (0) | |
| 16" Recovery | | | | | | |
| | 3 | 4.0' 6.0' | | Wet brownish gray fine sand w/some silt and coarse sand, trace of gravel. | A-2-4 (0) | |
| 17" Recovery | | | | | | |
| | 4 | 6.0' 8.0' | | Wet brownish gray fine to coarse sand w/trace of gravel and silt. | A-1-b (0) | |
| 21" Recovery | | | | | | |
| | 5 | 8.0' 10.0' | | Wet brownish gray coarse to fine sand w/some gravel, trace of silt. | A-1-b (0) | |
| 19" Recovery | | | | | | |
| (END) | | | | | | |

BORING NO. S # 8

SURFACE ELEV. + 5.28'

No blow counts boring done with geoprobe