

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 10

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS  
BORING LOCATION: STA. 1050+10, 28.1' Lt. CENTERLINE

R125-24

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
1/4/05	1	1.0' 2.0'		Wet brown silty fine sand w/some coarse sand, trace of organic matter.	A-2-4 (0)	
19" Recovery						
	2	2.0' 4.0'		Wet brownish gray fine sand w/some coarse sand and silt, trace of gravel.	A-2-4 (0)	
13" Recovery						
	3	4.0' 6.0'		Wet brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
20" Recovery						
	4	6.0' 8.0'		Saturated brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
19" Recovery						
( END )						

BORING NO. S # 10  
SURFACE ELEV. + 2.84'  
No blow counts boring done with geoprobe