

STATE OF DELAWARE  
 DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS  
 BORING LOCATION: STA. 1060+25, 41.7' Lt. CENTERLINE

R:25-26

BORING NO. S # 12

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
	1	1.0' 2.0'		Wet brown silty fine sand w/some coarse sand and organic matter, trace of gravel.	A-2-4 (0)	
22" Recovery						
	2	2.0' 4.0'		Wet brownish gray silty fine sand w/trace of coarse sand.	A-2-4 (0)	
23" Recovery						
	3	4.0' 6.0'		Wet brownish gray fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
21" Recovery						
	4	6.0' 8.0'		Wet brownish gray coarse to fine sand w/trace of gravel and silt.	A-1-b (0)	
24" Recovery						
	5	8.0' 10.0'		Saturated brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
24" Recovery						
( END )						

BORING NO. S # 12  
 SURFACE ELEV. + 4.98'

No blow counts boring done with geoprobe