

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
BORING LOCATION: STA. 1058+32, 694.9' Rt. CENTERLINE

R: 25-30

BORING NO. D # 10

| DAILY PROGRESS | SAMPLE NO. | DEPTH | BLOWS/6" | SAMPLE DESCRIPTION | CLASS/G.I. | REMARKS |
|-------------------|---------------|-------|----------|--|------------|---------|
| 12/29/04 | 1 | 0.8' | | Wet gray silty fine sand w/some coarse sand. | A-2-4 (0) | |
| | | 2.0' | | | | |
| | 2 | 2.0' | | Wet gray fine sandy silt w/some coarse sand. | A-4 (0) | |
| | | 4.0' | | | | |
| | 3 | 4.0' | | Saturated brown fine sand w/some silt, trace of coarse sand. | A-2-4 (0) | |
| | | 6.0' | | | | |
| | 4 | 6.0' | | Saturated brown fine sand w/trace of silt and coarse sand. | A-3 (0) | |
| | | 8.0' | | | | |
| | 5 | 8.0' | | Saturated brown fine sand w/some coarse sand, trace of silt and gravel. | A-3 (0) | |
| | | 10.0' | | | | |
| (END) | | | | | | |

BORING NO. D # 10
SURFACE ELEV. + 0.70'
No blow counts boring done with geoprobe