

STATE OF DELAWARE
 DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. D # 2

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
 BORING LOCATION: STA. 1079+33, 356' Rt. CENTERLINE

R125-49

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
12/30/04	1	1.0' 2.0'		Saturated brown silty fine sand w/some coarse sand, trace of organic matter.	A-2-4 (0)	
19" Recovery						
	2	2.0' 4.0'		Saturated brownish gray fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
20" Recovery						
	3	4.0' 6.0'		Saturated brownish gray silty fine sand w/trace of coarse sand.	A-2-4 (0)	
15" Recovery						
	4	6.0' 8.0'		Saturated brownish gray fine sand w/some coarse sand and silt, trace of gravel.	A-2-4 (0)	
17" Recovery						
	5	8.0' 10.0'		Saturated brownish gray fine sand w/some coarse sand, trace of silt and gravel.	A-3 (0)	
22" Recovery						
(END)						

BORING NO. D # 2
 SURFACE ELEV. + 2.69'
 No blow counts boring done with geoprobe