

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. D # 3

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
BORING LOCATION: STA. 1075+59, 618' Rt. CENTERLINE

R:25-50

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
12/30/04	1	1.0' 2.0'		Wet brownish gray silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
21" Recovery						
	2	2.0' 4.0'		Wet brownish gray fine to coarse sand w/trace of silt.	A-3 (0)	
23" Recovery						
	3	4.0' 6.0'		Saturated brownish gray fine sand w/some silt and coarse sand.	A-2-4 (0)	
24" Recovery						
	4	6.0' 8.0'		Saturated brownish gray fine sand w/trace of silt and coarse sand.	A-3 (0)	
14" Recovery						
	5	8.0' 10.0'		Saturated brownish gray fine sandy silt w/trace of coarse sand.	A-4 (0)	
21" Recovery						

(END)

BORING NO. D # 3
SURFACE ELEV. + 4.49'
No blow counts boring done with geoprobe