

R: 32-7

Bunting Nursery Pit Hole N2

May 4, 1988 Elev Top Hole 2'

Pit wall description Elev top 10'

9" Sand; slty; dk gry; m; scat gran  
- sharp contact

2' Sand; m-f; mott lt + dk brn; str less; looks burrowed  
- grad -

3' Sand; lt gry; m-crs; h.m lam in bottom 1'; crs + dk  
brown in bottom 6"

2' Sand; f; gry; w sorted; str less?

Hole N2

Elev 2'

Depth

Description

0-1

Sand; m-crs; lt-dk brn; w/org, spoil

1-1.5

Sand; m-f; or-brn; str less

1.5-2.5

Sand; m-crs; or brn; h.m lam, x-bd cn

2.5-2.7

Sand; f; slily cly; gry

2.7-3.0

Sand; v crs; abn gran; some v sml pbl; lt gry; some x-bd

3.0-4.5

Sand; m-f-m; lt gry; scat crs bd + h.m lam; scat  
gran + v sml pbl

4.5-6.0

Sand; f; scat sml pbl; few h.m lam; lt gry

6.0-7.5

same

7.5-8.25

same

8.25-9.0

Sand; m-crs; lt gry-or brn; x bd; some h.m lam  
scat pbl < 1cm;

9.0-10.0

same

10.0-10.5

Sand; m-crs; wh; abn h.m lam; x-bd; scat gran

10.5-12.0

Same; some slily cly zones?

12.0-13.5

No recover x

- 3.5-15.0 Sand; m; wh; v. soupy - poor recovery  
15.0-16.5 No recovery  
16.5-18.0 Sand; m-crs; wh; h.m km cn; some cly zones;  
dk gry w/ pbl < 2cm; feldspatic; few cly clsts  
18.0-23.0 No recovery  
23.0-24.5 Sand; crs; gry-wh; scat gran + v sml pbl; h.m cn.

Augered down to 50'

No samples

material appears to be same as above