

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 24

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 346+00, CENTERLINE

Oc 25-15

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/10/04	1	0.8'	1	Moist very loose brown fine sand w/some coarse sand and silt.	A-2-4 (0)	
			1			
			2			
		2.0'	2	22" Recovery		

	2	2.0'	2	Moist very loose brown fine to coarse sand w/some silt.	A-2-4 (0)	
			2			
			2			
		4.0'	4	22" Recovery		

	3	4.0'	6	Wet loose brown silty fine sand w/some coarse sand.	A-2-4 (0)	
			5			
			3			
		6.0'	2	18" Recovery		

	4	6.0'	6	Wet medium dense brownish gray silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
			5			
			18			
		8.0'	12	22" Recovery		

	5	8.0'	10	Wet medium dense brownish gray coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	
			10			
			10			
		10.0'	8	22" Recovery		

(END)						

was

BORING NO. B # 24
SURFACE ELEV. + 40.6'